



Photo 1 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
Concrete berm wall added at the Main Stack silage pad.



Photo 2 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
Collection tank for surface runoff between the T-Barn and Milking Barn.



Photo 3 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
Location of water leak/seepage below the concrete slab and collection tank.



Photo 4 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
Covered animal walkway with low curbing and adjacent storm drain.



Photo 5 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
2nd manure pit, with volume nearing capacity



Photo 6 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
View of the Main manure pit.



Photo 7 – Crosswinds Dairy, 98 Martell Rd., Alburgh, VT – 05/20/15
Manure stacking outside the Main pit.